

46

Project Resources Inc.

Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: 3697		
Property Address: 480 Mily roke St		
Owner: Martin & Anita. Miramont	rs	
Phone: 303 - 296 - 2479		
See all all		
Restoration Items in Question:		
Item:		
Item:		
Item:	·	
Item:		
Item:	,	
Item:		
Additional Comments:		
I agree restoration is completed, except as noted		
I do not agree restoration is completed .		
I agree that the sprinkler system is working properly following reinstallation by contractor		·
Master A Migun inter 7:5	11.05 Amusa	7/21/0
Owner's Signature Date	Contractor's Signature	Date

PROPERTY INFO	RMATION		DECISION CRITE	RIA
Property ID:	3697		Target Property?	Yes
House Number:	4801		Soil Sampled?	Yes
Street:	MILWAUKEE ST		Removal Required?	Yes
Address:	4801 MILWAUKEE ST	Find Record	Removal Complete?	
Unit:				
ZIP Code:	80216	•	SOIL SAMPLE RE	ESULTS
Neighborhood:	SWANSEA	a	Phase 4	
Zone:	R1		Arsenic Decision Value	84
OWNER INFORMA	ATION		Lead Decision Value	137
Owner Name:	MARTIN H & ANITA C MIRAMO	NTES		
Mailing Address:	4801 MILWAUKEE ST			
Mailing City State Zip:	DENVER CO 80216	ماد ماد المساح	OTHER SAMPLE	RESULTS
			Media Description	
			Arsenic	
			Lead	

Meagan Redfern

From:

OCARS Pro@uncc.org

Sent:

Tuesday, June 21, 2005 12:18 PM

To:

Meagan Redfern

Subject:

UNCC EMLCFM 2005/06/21 #00169 A0264008-00A NORM NEW

EMLCFM 00169 UNCCa 06/21/05 12:17 PM A0264008-00A NORM NEW STRT LREQ

Ticket Nbr: A0264008-00A

Original Call Date: 06/21/05 Time: 12:17 PM Op: MRE

Locate By Date : 06/23/05 Time: 11:59 PM Meet: N Extended job: N

State: CO County: DENVER City: DENVER

Addr: 4801 Street: MILWAUKEE ST

Grids: 03S068W13SW : 03S068W24NW : Legal: Y

Lat/Long: 39.785582/-104.952807 39.785582/-104.951006

: 39.783089/-104.952807 39.783089/-104.951006

Type of Work: SOIL EXCAVATION Exp.: N

Boring: N

Location: *LOC ENTIRE LOT * TO INCL. ALL EASEMENTS TO STREET Company: PROJECT RESOURCES INC. Type: OTHR

Caller: MEAGAN REDFERN Phone: (303)487-0377
Alt Cont: AMY JAMES Phone: (303)487-0377

Fax: Email: MREDFERN@PROJECTRESOURCESINC.COM

Done for: CORPS OF ENGINEERS/EPA

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA ABOVENT= ABOVE NET/MFN

MMO:

Members PCNDU0 = XCEL ENERGY-NORTH DENVER PSND14 = XCEL ENGY--APPT

SCHEDULE-- U

Members QLNCND0= QWEST LOCAL NETWORK (UQ) QLNCND1= QWEST LOCAL

NETWORK

Members SPRN01 = U.S. SPRINT TWTEL1 = TIME WARNER


TELECOM

Members WCG01 = WILTEL COMMUNICATION

You are responsible for contacting any other utilities that are not listed above

including the following tier 2 members not notified by the center:

DGTRN1 DIGATRON SECURITY (303)295-4369
DNVH20 DENVER WATER DEPT (303)628-6666
DNVPR1 DENVER PARKS & REC. (303)458-4839
DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001
SAWS01 SO ADAMS COUNTY H20,SANI (303)288-2646
WWMG01 WASTEWATER MGMT DIVISION (303)446-3744





Real Property Records

Date last updated: Friday, December 10, 2004

3 Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property Link to property sales information for this neighborhood Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential

Parcel: 0213321007000

Name and Address Information

Legal Description

MIRAMONTES, MARTIN H & ANITA C

4801 MILWAUKEE ST

CAWKERS ADD B13 L14 & 15

RESIDENTIAL

DENVER, CO 80216

Property Address:

Tax District

4801 MILWAUKEE ST

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	17700	1410		
Improvements	149100	11870		
Total	166800	13280	0	13280
Prior Year				
Land	17700	1410		
Improvements	149100	11870		
Total	166800	13280	0	13280

Style: One Story

Year Built: 1951

Building Sqr. Foot: 973

Bedrooms: 3

Baths Full/Half: 1/0

Basement/Finished: 297/282

Lot Size: 5,900

Zoning: R1

Reception No.: 0000092939

Recording Date: 10/04/90

Document Type: Warranty

Sale Price:

Mill Levy: 64.162





U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Martin and Anita Miramontes		
Property Address	4801 Milwaukee Street		
Property Identification Number	3697		

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)	63 sq. ft.	\$2.50	\$157.50
Trees			
Itemized shrubs/bushes	9	\$12.00	\$108.00
Total			\$265.50

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.


The total amount of \$265.50 has been received by the owner in the form of a replacement certificate, #615/6/to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

Property Owner's Signature

Date


Contractor's Signat

Date



Property Access Checklist

Property ID: 3697			STARTED ON: / /	
Property Address: 4801 Milwaykel		☐ WOR	K STARTED ON:/_/_ K COMPELTED ON:/_/_	
Property Owner: Marin & Pui-	a	Property R	lenter:	
Mailing Address: Miramo	nes	Home Pho	ne:	
		Fax:		
ļ		Cell/Pager:		
Home Phone: 303-296-2479		Additional	Information:	
Fax:	·			
Cell/Pager:		<u> </u>		
			T	
Notification Letter	Sent: 12	17/04	By: A.James	
Access Agreement	Signed: 1	716104	By: Martind Paita Miramorte	
Restoration Agreement	Signed:	119/05		
☐ Topsoil Sampling (if applicable)	/_	_/	By:	
☐ Disposal Sampling (if applicable)	/_	_/	By:	
Garden Sampling (if applicable)	/_	_/	By:	
☐ Utility Clearance	Called:	//_	By:	
Video/Photos (Before)	On:/	19/05	By: Keith Hughes	
☐ Video/Photos (During)	On:/		By:	
☐ Video/Photos (After)	On:/		By:	
☐ Video/Photos (30-Day)	On:/		By:	
Property Completion Agreement	Signed:		By:	
☐ Final Report	Issued:		By:	
		·		
Air Monitoring (as applicable)				
	<u>/_/_</u>	By:		
Results:			l l	
☐ Community ☐ Crew On:	//	By:		
Results:	·_ 	 		
		15		
Community Crew On:	<u>'_'_</u>	Ву:		
resum:				



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 3697	
Property Address: 4501 Milwawkee St.	
Owner: Martin & Paita Miramontes	
Phone: 303 - 296 - 2479	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

item:	
	Decorative bricks and yard ornaments.
Item:	
Item:	
Item:	
Item:	
Manage	
item:	
Item:	
leni;	
Item:	



item:

Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

ltem:			
item:		·	
Item:	:		
ltem:			
Item:			
•	Items To Be Remo	oved By Contractor Duri (Use additional sheets as	ng Remediation And <u>Replaced</u> necessary)
Item:	NA		
item:	NA		
	NA		
Item:	NA		
item:	NA		
Item: Item:	NA		
Item: Item: Item:	NA		



Landscape Inventory (Use additional sheets as necessary)

ltem	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	3,367	Square Feet	
Number of trees > 2 inch trunk diameter	NA		
Number of trees < 2 inch trunk diameter	NA		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	none		Zones:
Number of and total size of all gardens / flower beds.	# Of Beds:		Fr² Of Beds: <u>63 5F</u>
: Attach a sketch of relative sizes and locations.	# Of Gardens:	-	Ft ² Of Gardens:



Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	s	Total Ft ² Of Beds To Be Replaced With Certificate: 9 Rosebushes 63 5F
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.	NIA	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	2,685	SF	Total Ft ² Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Ft ² :	SF	Sod: Brown Mulch: Red Mulch:
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red: NA Brown: 1 5P



Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Fr ² Of Rock:	SF	Large: NA Medium: NA Small (pea gravel): 168 SF Driveway Gravel: NA
Agreed upon area to be replaced with no groundcover.	Total Fr ² With No Groundcover: 335	·	

	Additional Comments / Instructions:
1	Additional Confinence / insudencia.
1	
·	*
;	
, i	



	· · · · · · · · · · · · · · · · · · ·		
	Additional Commen	ts / Instructions Continued:	
Ou ne Landsc	will sen	ove some kejere Job	Starts
	•	•	
		•	
·			
pre existing damag	if Owner does not want PRI ge. By checking this box P duding foundation cracks or	RI is not responsible for a	ation walls and possible ny damage done to the
T agree	I do not agree	☑ I agree	☐ I do not agree
Martin H Owner's Signature	Myemont	Contractor's Signatu	eugo 1-19-05 re Date

Property Check-List

Yes/No

1. None Sprinkler System?

2. VES Basement Photos?

3. No Photos of Water Meter?

4. 105 All 3 Signatures?

5. Number of Trees?

6. Approximate Voucher Size?

7. Are all trees and bushes clearly labeled on the map?

8. MYR Clotheslines marked and is it removed or replaced?

9. LES House accessible for equipment?

10. _____ Owner clear of everything they will need to remove?

11. \(\frac{1}{2}\) Owner clear the dates when we call him are approximate?

12. A second walk through done on the property to double check the map by the individual who did the video/photos?

Owner has started to move stuff



Property Access Checklist

Property ID: 3697			STARTED ON: _/_/	
Property Address: 4801 Milw	aukee	☐ WORK	COMPELTED ON:/_/_	
Property Owner: Marin & Au-	a	Property R		
Mailing Address: Muramo	intes	Home Phor	le:	
-		Fax:		
Home Phone: 303-296-2479		Cell/Pager: Additional Information:		
Fax:				
Cell/Pager: 303)995 - 3795	cell			
Notification Letter	Sent: 12	17/04	By: A James	
Access Agreement	Signed: 12	16104	By: Martind Asita Miramorto	
Restoration Agreement	Signed:	119/05	By: Martin Miranentes	
☐ Topsoil Sampling (if applicable)	//		Ву:	
☐ Disposal Sampling (if applicable)	'		Ву:	
Garden Sampling (if applicable)			By:	
Utility Clearance	Called://		Ву:	
☑ Video/Photos (Before)	on: 1/19/05		By: Keith Hughes	
☐ Video/Photos (During)	On:/		ву:	
☐ Video/Photos (After)	On:/		By:	
☐ Video/Photos (30-Day)	On:/		Ву:	
Property Completion Agreement	Signed:	<i>!</i> /	Ву:	
☐ Final Report	Issued:	//_	Ву:	
Air Monitoring (as applicable)				
	//_	By:		
Results:				
Community Crew On:	//_	By:		
Results:				
· · · · · · · · · · · · · · · · · · ·	//	By:		
Results:				



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 3697
Property Address: 4801 Milwawkee St.
Owner: Martin & Paita Miramontes
Phone: 303 - 296 - 2479

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	
	Decorative bricks and yard ornaments.
item:	
Item:	
itein;	į
item:	
Item:	
item:	
ltem:	
Item:	



Item:

Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

Item:	
Item:	·
item:	·
Item:	·
Item:	rendered de la composition della composition de
	Items To Be Removed By Contractor During Remediation And <u>Replaced</u> (Use additional sheets as necessary)
Item:	
	NIA
ltem:	NIA
Item:	NIA
	NIX
Item:	N/H
Item:	N/A
Item:	N/A



Landscape Inventory (Use additional sheets as necessary)

ltem	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	3,367	Square Feet	
Number of trees > 2 inch trunk diameter	NA		
Number of trees < 2 inch trunk diameter	NIA		·
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	none		Zones:
Number of and total size of all gardens / flower beds.	# Of Beds:		Fr ² Of Beds: <u>63 5F</u>
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft ² Of Gardens:



Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft ² Of Beds To Be Replaced With Certificate: 9 Rosebushes 63 5F
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.	NIA	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	2,685	SF	Total Ft ² Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Ft ² :	SF	Sod: Brown Mulch:
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red: NA Brown: 1 SP



Froject Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Large: _NA Medium: _NA Small (pea gravel):
Agreed upon area to be replaced with no groundcover.	Total Fr ² With No Groundcover:	·	

	Additional Comments / Instructions:	,
		·
į		



Additional Comments / Instructions Continued:	
Owner will serrove some Landscaping bricks kepere Job starts	
	ļ
Check the box if Owner does not want PRI to document interior foundation walls and possi pre-existing damage. By checking this box PRI is not responsible for any damage done to interior of house, including foundation cracks or fissures.	
☐ I agree ☐ I do not agree ☐ I do not agree)
Matin It Miremonts Come Reyco 1-19- Owner's Signature Date Confisctor's Signature Date	<u>05</u>

Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: Martin & Anita Mir	Phone: 303-296-2479	
Addresses of	Address:	4801 Milwaukee St
Properties covered by this Agreement:	Address:	
	Address:	

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

Page 1 of 2		
-------------	--	--

Consentimiento para el Acceso de la Propiedad

DERECHO A ENTRAR LA PROPIEDAD

El otorgante (dueño/a de la propiedad) le da permiso y autoriza la Agencia para la Protección del Medio Ambiente de los Estados Unidos (EPA) y/o a sus representantes autorizados (Cesionario) a entrar y a llevar a cabo algunas actividades ambientales en la propiedad a continuación:

Dueño/a de la Propied Martin & Anita Mi	Numero de Leiesono:	
Dirección de las Propiedades Cubiertas por este Acuerdo:	Dirección: 4801 Milwaukee St	
	Dirección:	
	Dirección:	

PROPÓSITO DE LAS ACTIVIDADES AMBIENTALES

La EPA solicita el acceso a tomar muestras de tierra y a remover la tierra en su propiedad que tiene concentraciones altas de arsénico y/o plomo que podrían ser_peligrosos a su_salud. La tierra será removida y el(las) área(s) excavada(s) serán reemplazadas con materiales limpios. Este trabaja estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de la EPA contactará al Otorgante personalmente para discutir el trabajo que se va a realizar en la propiedad del Otorgante. El Otorgante tendrá la oportunidad de examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termine, el Otorgante revisará el trabajo, confirmará su terminación y cumplirá con su aprobación. Después de la terminación del trabajo, el Otorgante recibirá un documento escrito por la EPA que indicará que la propiedad ha sido remediada.

ACCIONES DE LA ACTIVIDAD AMBIENTAL

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contractores y subcontractores el derecho a entrar la propiedad, en tiempos razonables y sin noticia anterior, para el único propósito a realizar el trabajo aquí descrito. Este acceso debería persistir en efecto hasta que el trabajo haya sido terminado. El Ortogante también está de acuerdo con:

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

I grant access to my properties

I do not grant access to my properties

| July | July

Page 2 of 2

- Remover obstrucciones, incluyendo botes, remolque, vehículos, juguetes de niños, montones de madera, casas de perros, etc.
- Remover bulbos de flores, u otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener el reemplazo de vegetación, incluyendo la aplicación de fertilizante, subsecuente a la riega inicial por la EPA, a menos que el uso de agua esté restringido por la Junta de Agua de Denver.
- Seguir las recomendaciones de la guía de Salud y Seguridad de la EPA;
- Si la propiedad es rentada, asistir a la EPA a obtener la aprobación del inquilino para tener acceso a la propiedad dende se va a llevar a cabo el trabajo, si acaso la EPA no logra obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad, incluyendo el área exterior y interior del edificio.


ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividad o trabajo hecho, o equipo que va a llevar a cabo las actividades en la propiedad, o arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor llame al centro de comando de VB/I-70 a (303) 487-0377.

Si, yo permito acceso a mi propiedad.	No permito acceso a mi	propiedad.
Martin H Miranorter 126-6	Monte Misamo	√13-60-0 Fecha
☑ Me gustaría ser presente durante de cualquie	r colección de muestras.	
☐ Mi propiedad tiene un sistema de regar planta	as y sacate (sprinkler system).	
	•	

Página 2 of 2




Habiliandshadhllassillashladdinallilashlad

VB/I-70 Command Post

10 E. 55th Avenue

Denver, CO 80216



TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1035175

Sľ	TE NAME:	VASQUEZ BOULEVARD AND I-70
DC	CUMENT DATE:	07/21/2005
Dυ	e to one of the fo	DOCUMENT NOT SCANNED lowing reasons:
	PHOTOGRAPHS	
	3-DIMENSIONAL	
	OVERSIZED	
V	AUDIO/VISUAL	
	PERMANENTLY	BOUND DOCUMENTS
	POOR LEGIBILIT	Υ
	OTHER	
	NOT AVAILABLE	
	· · · · · · · · · · · · · · · · · · ·	MENTS NOT TO BE SCANNED Data Validation, Sampling Data, CBI, Chain of Custody)
DC	CUMENT DESCR	IPTION:
	2 - DVDs OF PRO	PERTY VIDEO, PROPERTY #3697